

## Inspection Photos

Location Name: Hertzke N - 65N67W /1SWNE

Location #: 310579



**Photo #1**  
Facing East

Produced water vault load line has been capped



**Photo #2**  
Production Facility Sign  
facing SE

P&A wells have been removed from sign

