

Well Name : Robertson 19-1 2
API # : 067-08778



Photo 1: Wellhead sign previous inspection.



Photo 2: Wellhead sign.

Well Name : Robertson 19-1 2
API # : 067-08778



Photo 3: Production tank with no visible labels previous inspection.



Photo 4: Visible signage installed at production tank.

Well Name : Robertson 19-1 2
API # : 067-08778



Photo 5: Steel post with concrete base previous inspection.



Photo 6: Steel post and concrete base removed.

Well Name : Robertson 19-1 2
API # : 067-08778



Photo 7: Unused equipment inside wellhead fencing previous inspection.



Photo 8: Unused equipment removed.

Well Name : Robertson 19-1 2
API # : 067-08778



Photo 9: Location overview.



Photo 10: Location overview.