

**Inspection Photo**  
**Miller 14A-32-691**  
**API# 045-17925**  
**Inspection # 689301059**



**Location photo # 1**



**Location photo #2**

**Inspection Photo  
Miller 14A-32-691  
API# 045-17925  
Inspection # 689301059**



**Location photo # 3 Peeling sign on tank**



**Location photo # 4 Faded sign, and peeling sign on tanks**

**Inspection Photo**  
**Miller 14A-32-691**  
**API# 045-17925**  
**Inspection # 689301059**



**Location photo # 5 storm water erosion on SE corner of Tank Battery**



**Location photo #6 storm water erosion on SE corner of Tank Battery**

**Inspection Photo**  
**Miller 14A-32-691**  
**API# 045-17925**  
**Inspection # 689301059**



**Location photo # 7 storm water erosion on SE corner of Tank Battery**

**Location photo #8 storm water erosion on SE corner of Tank Battery**