

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
05/01/2018

Submitted Date:  
05/08/2018

Document Number:  
689500772

**FIELD INSPECTION FORM**

Loc ID 335706 Inspector Name: GRANAHAN, KYLE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

19 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: 600 E EXCHANGE AVE  
City: FORTH WORTH State: TX Zip: 76164

**Contact Information:**

| Contact Name     | Phone | Email                         | Comment             |
|------------------|-------|-------------------------------|---------------------|
| Dooling, Jessica |       | Jessica_Dooling@xtoenergy.com | Piceance Creek insp |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 287686      | WELL | PR     | 05/31/2012  | GW         | 103-10952 | PICEANCE CREEK UNIT 296-17A7 | PR          |
| 287689      | WELL | PR     | 10/18/2009  | GW         | 103-10951 | PICEANCE CREEK UNIT 296-17A8 | PR          |
| 287690      | WELL | PR     | 05/01/2012  | GW         | 103-10950 | PICEANCE CREEK UNIT 296-17A5 | PR          |
| 287691      | WELL | PR     | 05/01/2012  | GW         | 103-10949 | PICEANCE CREEK UNIT 296-17A6 | PR          |
| 287692      | WELL | PR     | 02/01/2018  | GW         | 103-10948 | PICEANCE CREEK UNIT 296-17A9 | PR          |
| 287693      | WELL | PR     | 07/13/2010  | GW         | 103-10947 | PICEANCE CREEK UNIT 296-17A1 | PR          |
| 287694      | WELL | PR     | 05/01/2012  | GW         | 103-10946 | PICEANCE CREEK UNIT 296-17A2 | WK          |
| 287695      | WELL | PR     | 05/01/2012  | GW         | 103-10945 | PICEANCE CREEK UNIT 296-17A4 | PR          |
| 287696      | WELL | PR     | 05/01/2012  | GW         | 103-10944 | PICEANCE CREEK UNIT 296-17A3 | PR          |

**General Comment:**

On location to conduct routine inspection

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |  |       |
|--------------------|----------------------|--|-------|
| Type               | BATTERY              |  |       |
| Comment:           | Present/complete     |  |       |
| Corrective Action: |                      |  | Date: |
| Type               | TANK LABELS/PLACARDS |  |       |
| Comment:           | Present/complete     |  |       |
| Corrective Action: |                      |  | Date: |
| Type               | WELLHEAD             |  |       |
| Comment:           | Present/complete     |  |       |
| Corrective Action: |                      |  | Date: |

Emergency Contact Number:

Comment: 970-675-4117

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |          |  |       |
|--------------------|----------|--|-------|
| Type               | LOCATION |  |       |
| Comment:           |          |  |       |
| Corrective Action: |          |  | Date: |

**Equipment:**

| Type:                |                                      |  | corrective date |
|----------------------|--------------------------------------|--|-----------------|
| Other                | # 1                                  |  |                 |
| Comment:             | Telecom unit                         |  |                 |
| Corrective Action:   |                                      |  | Date:           |
| Ancillary equipment  | # 4                                  |  |                 |
| Comment:             | Chem tote with secondary containment |  |                 |
| Corrective Action:   |                                      |  | Date:           |
| Deadman # & Marked   | # 12                                 |  |                 |
| Comment:             |                                      |  |                 |
| Corrective Action:   |                                      |  | Date:           |
| Plunger Lift         | # 9                                  |  |                 |
| Comment:             |                                      |  |                 |
| Corrective Action:   |                                      |  | Date:           |
| Horizontal Separator | # 1                                  |  |                 |

|                    |   |       |  |
|--------------------|---|-------|--|
| Comment:           | One separator/gas meter skid unit for all wells |       |  |
| Corrective Action: |   | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type             | Tank ID | SE GPS |
|--------------------|---|----------|------------------|---------|--------|
| CONDENSATE         | 1 | 400 BBLS | HEATED STEEL AST |         | ,      |
| Comment:           |   |          |                  |         |        |
| Corrective Action: |   |          |                  |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  |       |
|                    |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  |       |
|                    |  | Date: |

| Inspected Facilities  |   |       |      |             |           |         |    |               |    |
|-----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 287686  | Type: | WELL | API Number: | 103-10952 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |    |               |    |
| Comment:              | PR - via plunger lift, no leaks/venting - remote pressure monitoring present. |       |      |             |           |         |    |               |    |
| Corrective Action:    |   |       |      | Date:       |           |         |    |               |    |
| Facility ID:          | 287689  | Type: | WELL | API Number: | 103-10951 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |    |               |    |
| Comment:              | PR - via plunger lift, no leaks/venting - remote pressure monitoring present. |       |      |             |           |         |    |               |    |
| Corrective Action:    |   |       |      | Date:       |           |         |    |               |    |
| Facility ID:          | 287690  | Type: | WELL | API Number: | 103-10950 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |    |               |    |
| Comment:              | PR - via plunger lift, no leaks/venting - remote pressure monitoring present. |       |      |             |           |         |    |               |    |
| Corrective Action:    |   |       |      | Date:       |           |         |    |               |    |
| Facility ID:          | 287691  | Type: | WELL | API Number: | 103-10949 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |    |               |    |
| Comment:              | PR - via plunger lift, no leaks/venting - remote pressure monitoring present. |       |      |             |           |         |    |               |    |
| Corrective Action:    |   |       |      | Date:       |           |         |    |               |    |
| Facility ID:          | 287692  | Type: | WELL | API Number: | 103-10948 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |    |               |    |
| Comment:              | PR - via plunger lift, no leaks/venting - remote pressure monitoring present. |       |      |             |           |         |    |               |    |
| Corrective Action:    |   |       |      | Date:       |           |         |    |               |    |
| Facility ID:          | 287693  | Type: | WELL | API Number: | 103-10947 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |    |               |    |
| Comment:              | PR - via plunger lift, no leaks/venting - remote pressure monitoring present. |       |      |             |           |         |    |               |    |
| Corrective Action:    |   |       |      | Date:       |           |         |    |               |    |
| Facility ID:          | 287694  | Type: | WELL | API Number: | 103-10946 | Status: | PR | Insp. Status: | WK |
| <b>Workover</b>       |   |       |      |             |           |         |    |               |    |
| Comment:              | Swabbing unit on location, swabbing well to unload and put back on line.      |       |      |             |           |         |    |               |    |
| Corrective Action:    |   |       |      | Date:       |           |         |    |               |    |
| Facility ID:          | 287695  | Type: | WELL | API Number: | 103-10945 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |   |       |      |             |           |         |    |               |    |
| Comment:              | PR - via plunger lift, no leaks/venting - remote pressure monitoring present. |       |      |             |           |         |    |               |    |

|                              |   |       |      |             |           |         |    |               |    |
|------------------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Corrective Action:           |   | Date: |      |             |           |         |    |               |    |
| Facility ID:                 | 287696  | Type: | WELL | API Number: | 103-10944 | Status: | PR | Insp. Status: | PR |
| <b><u>Producing Well</u></b> |   |       |      |             |           |         |    |               |    |
| Comment:                     | PR - via plunger lift, no leaks/venting - remote pressure monitoring present. |       |      |             |           |         |    |               |    |
| Corrective Action:           |   | Date: |      |             |           |         |    |               |    |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 |                         |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
| Ditches          |                 |                         |                       |               |                          |         |
| Sediment Traps   |                 |                         |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |

Comment: No sediment flow evident

Corrective Action:

Date: \_\_\_\_\_

**Pits:**      NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 689500773    | Location    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4456030">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4456030</a> |