

Inspection Photos

05/08/2018

Operator: PRE RESOURCES INC - 10241

Location ID: 390648

Inspection Doc. Number: 682503308

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PRE RESOURCES INC - 10241
Location ID: 390648



Photo 1: Photo taken from the location, facing west. Photo shows reclamation in process. It is noted that vegetation seen here is predominantly undesirable species such as cheatgrass.



Photo 2: Photo taken from the location. Photo shows vegetation is predominantly cheatgrass.



Photo 3: Photo taken from the access road. Photo shows additional reclamation activities appear to have been conducted.