



Event Log

Intersection		DP	CR	C	RD	DD	Intersection		DP	CR	C	RD	DD		
1	Start Job	9:24:13	3.112	0.000	0.000	8.562	11.45	2	Pump Spacer 1	9:24:17	3.112	0.000	0.000	8.470	11.37
3	Pump Spacer2	9:27:52	290.0	4.997	14.17	8.303	11.92	4	Pump Cement	9:30:20	0.195	0.000	0.000	11.02	-0.766
5	Clean Lines	9:46:25	1.167	0.000	46.09	9.689	10.74	6	Drop Bottom Plug	9:46:55	1.167	0.000	0.000	9.583	10.49
7	Pump Displacement	9:46:58	1.167	0.000	0.000	9.552	10.46	8	Bump Plug	10:11:12	-1.751	0.000	111.1	7.993	8.698
9	Open MSC	10:36:38	132.5	0.000	0.000	7.062	9.215	10	Pump Spacer 1	11:17:08	-2.723	0.000	0.000	8.452	8.315
11	Pump Lead Cement	11:21:08	32.29	0.000	0.000	11.16	8.269	12	Clean Lines	11:33:01	1.167	0.000	36.45	9.576	13.86
13	Drop Top Plug	11:35:41	0.195	0.000	0.000	9.271	8.376	14	Pump Displacement	11:35:45	0.195	0.000	0.000	9.195	8.361
15	Bump Plug	11:52:12	2288	0.000	74.71	9.317	8.345	16	Close MSC	11:52:19	2296	0.000	74.71	9.348	8.315
17	End Job	11:52:35	2299	0.000	74.71	9.363	8.453								

Customer:
Well Description:

Job Date:
UWI:

Ticket #:

HALLIBURTON
CemWin v1.1.0
29-Dec-99 11:58

RECEIVED

01119440

304-842-8936