

Inspection Photos

Location Name: 70 Ranch Laura-65N63W20SESW

Location ID: 332694



Photo 1: Wellheads, looking S



Photo 2: Stained soil at 70 Ranch Laura 24-20

