

**Inspection Photo
STI 29-7C (A29NE)
API# 045-11494
Inspection # 689301069**



Location photo # 1



**Location photo # 2, Holes in tank battery
liner**

**Inspection Photo
STI 29-7C (A29NE)
API# 045-11494
Inspection # 689301069**



Location photo # 3, holes tank battery liner



Location photo # 4, holes tank battery liner

**Inspection Photo
STI 29-7C (A29NE)
API# 045-11494
Inspection # 689301069**



Location photo # 5, stained rock in tank battery liner



Location photo # 6, stained rock in tank battery liner

**Inspection Photo
STI 29-7C (A29NE)
API# 045-11494
Inspection # 689301069**



Location photo # 7, stained rock in tank battery liner



Location photo # 8, stained rock in tank battery liner

**Inspection Photo
STI 29-7C (A29NE)
API# 045-11494
Inspection # 689301069**



**Location photo # 9, stained rock in tank
battery liner**



**Location photo # 10, stained rock in tank
battery liner**