

Inspected Facilities

Facility ID: 454307 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: COGCC followup inspection to spill ID 454307 at abandonment of Sitzman 1 Tank Battery. Remediation Project 11252 was approved on 4/24/2018. Operator is staging equipment to begin soil remediation in accordance with the approved Form 27. At least two domestic water wells appear to be adjacent the location. Operator is advised that due to the proximity of the release to the water wells, a groundwater assessment will be necessary if impacted soil extends to groundwater. Operator is requested to provide a Form 27 Supplemental Report upon completion of the onsite soil remediation and groundwater assessment.

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____