

Inspection Photos
Location Name: UPRR PAN AM D #6
Facility ID #244388



Photo 1. Wellhead, Unmarked risers, stained soil, pumjack guard not attached



Photo 2. Tank battery