

Final Reclamation Inspection

May 4, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-17652

Inspection Document #: 682403546

Weld County, CO

NWNW Section 22 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MARRS RED #VV 22-4
API: 05-123-17652



Photo 1. Photo taken from the well location, facing South. Alfalfa crop has not re-established and there was undesirable weed species observed (Kochia rosettes).