


IMAGE COURTESY OF GOOGLE EARTH 2017

**LEGEND**

- MONITORING WELL
  - DESTROYED MONITORING WELL
  - METER HOUSE
  - SURVEYED GROUNDWATER FLOW DIRECTION
  - FENCE
  - EXCAVATION EXTENT
  - BERM
  - RELATIVE GROUNDWATER ELEVATION CONTOUR
- CONTOUR INTERVAL = 0.50 FEET  
GRADIENT = 0.01 FEET/FOOT

GROUNDWATER ELEVATIONS WERE MEASURED ON MARCH 2, 2018.  
NM: NOT MEASURED



**FIGURE 2**  
**GROUNDWATER ELEVATION CONTOUR MAP**  
 DUBACH 16-4, THESING 9-4  
 NESE SEC 4-T3N-R66W  
 WELD COUNTY, COLORADO  
 KERR-MCGEE OIL & GAS ONSHORE LP

