

Inspection Photos
Location Name: CHAMPLIN 117 AMACO C#6
Facility ID # 269108




Photo 3. Unmarked riser




Photo 2. Unused equipment

will remove tank

are not responsive to our multiple requests.



in-use
Connected to
flowline - used
to hot oil + pressure
flowline + pressure
test line

Inspection Photos
Location Name: CHAMPLIN 117 AMACO C#6
Facility ID # 269108



Photo 1. Wellhead, unmarked riser




Photo 2. Tank battery

