

Inspection Photos
Location Name: Brown NW-2 Pad
Location ID: 427488



Photo 1: Location, looking SW



Photo 2: Wellheads, looking NE

Inspection Photos
Location Name: Brown NW-2 Pad
Location ID: 427488



Photo 3: Stained soil at wellhead



Photo 4: Stained soil at treater in house

Inspection Photos
Location Name: Brown NW-2 Pad
Location ID: 427488



Photo 5: Weed debris near heater units

