

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2018

Submitted Date:

04/27/2018

Document Number:

691400241**FIELD INSPECTION FORM**Loc ID 330751 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| Precup, Jim | | james.precup@state.co.us | |
| , | | COGCCinspections@anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 251755 | WELL | SI | 05/01/2017 | GW | 123-19559 | SPERL 16-2A | SI |
| 434564 | WELL | PR | 03/03/2014 | OW | 123-38258 | CLINE 27N-2HZ | PR |
| 434565 | WELL | PR | 03/03/2014 | OW | 123-38259 | CLINE 1N-2HZ | PR |
| 434566 | WELL | PR | 03/03/2014 | OW | 123-38260 | CLINE 26C-2HZ | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Separator | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Calibration log shows last calibration in 2015. | | |
| Corrective Action: | Measure gas per Rule 329. | Date: | 05/27/2018 |
| Type: Horizontal Heater Treater | # 8 | | |

| | | | |
|-------------------------------|------|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 11 | | |
| Comment: | | Date: | |
| Corrective Action: | | Date: | |
| Type: Compressor | # 3 | | |
| Comment: | | Date: | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 4 | | |
| Comment: | | Date: | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|---------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | BV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 210 BBL |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|-----------------------------------|---------------------|---------------------|-------------|--------|
| | | | | | |
| Comment: | Shares berm with crude oil tanks | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| METHANOL | 1 | OTHER | OTHER | | , |
| Comment: | Steel tank above ground on stand. | | | | |
| Corrective Action: | | | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 500 GAL. |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspector Name: Beardslee, Tom

| | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 5 | 300 BBLs | STEEL AST | | 40.163970,-104.854680 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Inspected Facilities

Facility ID: 251755 Type: WELL API Number: 123-19559 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: PRODUCTION RECORDS

Comment:

Corrective Action:

Date:

BradenHead

Comment: Plumbed to surface

Corrective Action:

Date:

Facility ID: 434564 Type: WELL API Number: 123-38258 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Plumbed to surface

Corrective Action:

Date:

Facility ID: 434565 Type: WELL API Number: 123-38259 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Plumbed to surface.

Corrective Action:

Date:

Facility ID: 434566 Type: WELL API Number: 123-38260 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Plumbed to surface.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401623505 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4448172 |
| 691400242 | LOC PICS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4448159 |