

697-21A 23
Api: 05-045-14718
Inspection # 689701342




Location photo

697-21A 23
Api: 05-045-14718
Inspection # 689701342



Labels on container are faded and peeling.

697-21A 23
Api: 05-045-14718
Inspection # 689701342



Labels on container are faded and peeling.