

Inspection Photo
Jolley KP 433-21
API# 045-20273
Inspection # 689301103



Location photo # 1



Location photo # 2, Tank capacity missing

**Inspection Photo
Jolley KP 433-21
API# 045-20273
Inspection # 689301103**



Location photo # 3, Tank capacity missing



Location photo # 4, Tank capacity missing

**Inspection Photo
Jolley KP 433-21
API# 045-20273
Inspection # 689301103**



Location photo # 5, stained ground near separators



Location photo # 6, Stained ground near separators