

Inspection Photos

Location Name: Edwards - 65N67W / 9NWSE

Location #: 331067



Photo #1

Edwards 33-9 (API 05-123-20104) P&A wellsite

Facing SW

Flowline riser is unmarked and not LO/TO. Will need to be removed



Photo #2

Edwards 33-9 (API 05-123-20104) Battery

Facing NW

South tank was for this well.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Edwards - 65N67W / 9NWSE

Location #: 331067



Photo #3

Edwards 33-9 (API 05-123-20104) Separator

Facing N

