

# Final Reclamation Inspection

May 9, 2018

Operator: PETERSON ENERGY OPERATING INC #68710

Location ID: 432355

Inspection Document #: 682403562

Weld County, CO

NESE Section 32 T4N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: MARKHAM #33-32D, 44-32D

Location ID: 432355



**Photo 1.** Photo taken from the former battery location, facing South. No evidence of equipment at location. Battery location is located along the corner of a pivot field which does not appear to be included as part of the crop production (turf farm). Operator will be responsible and shall comply with reclamation rules if this portion is included as part of the crop production.



**Photo 2.** Photo taken from the former well location, facing Northwest. Appears the well location is fallow at the time of this inspection. See comments under Photo 1.