

Inspection Photos

Location Name: Sitzman 1 Tank Battery Spill ID: 454307, API: 05-123-11421

Complaint #200445872 Inspection Date: 05/15/2018



Photo 1 – View of domestic water well vault/sump for water well permit no. 276778. Well casing is open hole in sump. Motor has seized and a sample was not collected.



Photo 2 – Second view of domestic water well vault/sump for well permit no. 276778 showing pressure tanks.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sitzman 1 Tank Battery Spill ID: 454307, API: 05-123-11421

Complaint #200445872 Inspection Date: 05/15/2018



Photo 3 – Surface view of water well vault/sump location for water well permit no. 276778, looking east toward excavation for remediation at Sitzman #1 tank battery.



Photo 4 – View from north end of excavation at former Sitzman 1 tank battery, looking south. Excavation is approximately 80 feet east of water well permit no. 276778.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sitzman 1 Tank Battery Spill ID: 454307, API: 05-123-11421

Complaint #200445872 Inspection Date: 05/15/2018



Photo 5 – View of hydrant at well vault/sump for domestic water well permit no. 202929A which supplies the residence. Water sample collected from hydrant in photo.



Photo 6 – Purge water from water well no. 202929A just prior to sample collection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources