

Inspection Photos
Location Name: MARTIN T HART "H" 1
Facility ID #241041



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos
Location Name: MARTIN T HART "H" 1
Facility ID #241041



Photo 3. Unmarked riser near crude oil tank load out.



Photo 4. Unmarked riser near transfer pump

Inspection Photos
Location Name: MARTIN T HART "H" 1
Facility ID #241041



Photo 5. Unmarked riser near heated treater