

**Inspection Photos**  
**Location Name: Artist - 65N67W / 11NWNE**  
**Location #: 330118**



**Photo #1**

Artist 11-12 (API 05-123-18431) wellhead  
Facing S

**Weeds, unused equipment**



**Photo #2**

Artist 11-12, Swafford 11-11 Battery  
Facing SW



## Inspection Photos

Location Name: Artist - 65N67W / 11NWNE

Location #: 330118



**Photo #3**

Meter House door is missing  
facing W

**Mechanical Conditions**

