

Interim Reclamation Inspection

May 14, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 441250

Inspection Document #: 682403584

Weld County, CO

NESE Section 26 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WILSON RANCH /12N-
27HZ
Location ID: 441250



Photo 1. Photo taken of the southeast well location, facing North. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations at the battery location and portions of the well location, with the evidence of drilling rows and straw crimped mulch. Germination was apparent throughout the interim areas, as well as Kochia rosettes. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards.



Photo 2. Photo taken of the southeast well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: WILSON RANCH /12N-
27HZ
Location ID: 441250



Photo 3. Photo taken of the northwest well location, facing South. Appears portions of the eastern well location are not needed for production operations. Operator shall comply with Rule 1003 standards if these areas are no longer needed.



Photo 4. Photo taken of the northern well location, facing Northeast. See comments under Photo 1.

Inspection Photos
Location Name: WILSON RANCH /12N-
27HZ
Location ID: 441250



Photo 5. Photo taken of the southeast battery location, facing West. See comments under Photo 1.



Photo 6. Photo taken of the southeast battery location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: WILSON RANCH /12N-
27HZ
Location ID: 441250



Photo 7. Photo taken of the northwest battery location, facing South. See comments under Photo 1.



Photo 8. Photo taken of the northwest battery location, facing East. See comments under Photo 1.