

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2018

Submitted Date:

05/16/2018

Document Number:

677900333

**FIELD INSPECTION FORM**

Loc ID 303379 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253014	WELL	PR	06/01/2015	GW	125-06891	GRIGSBY 2-32	PR

**General Comment:**

[Routine Inspection](#)

**Location**

**Lease Road:**

Type	Access				
comment:	Access wellhead through farm ground				
Corrective ActionL				Date:	

Overall Good:

**Signs/Marker:**

Type	WELLHEAD				
Comment:	Lease sign by wellhead				
Corrective Action:				Date:	

Emergency Contact Number:

Comment:					
Corrective Action:				Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD				
Comment:	Pipe fence around wellhead				
Corrective Action:				Date:	

**Equipment:**

					corrective date
Type: Gas Meter Run	# 0				
Comment:					
Corrective Action:				Date:	
Type: Vertical Separator	# 0				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 0				
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

**Flaring:**

Type					
------	--	--	--	--	--

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 253014 Type: WELL API Number: 125-06891 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Central meter run for \(Sharp 12-32, Grigsby 2-32, 14-32, 23-32, 24-32\) 1280' WSW of wellhead](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: [Location is farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT