

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2018

Submitted Date:

05/16/2018

Document Number:

674104397**FIELD INSPECTION FORM**Loc ID 307511 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 600 E EXCHANGE AVECity: FORTH WORTH State: TX Zip: 76164**Contact Information:**

Contact Name	Phone	Email	Comment
Amato, Joe	719-845-2110	josephamato@tcenergy.us	Environmental Manager
		ediefitzgerald@tcenergy.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217764	WELL	PA	05/29/2003		071-06543	GOLDEN EAGLE 29-09 (SD-2)	RI

General Comment:

This is a Final Reclamation Inspection for PA Well API#071-06543; Records for this well are very sparse. APD was Approved for Basin Resources in January 1998. Form 6S Doc#400496461 was Approved using casing data off the APD and the day before XTO took over (5/29/2003) as the Plugging date with attached picture of cemented casing and surveyors mine map." This is a Follow Up to Insp Doc#680102753 Dated 3/7/18; CAs from that Inspection have been Resolved. This is an AMI Inspection

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed _____

Gravel removed Pass

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured Pass

Compaction alleviation Pass Dust and erosion control Pass

Non cropland: Revegetated 80% Pass Cropland: perennial forage _____

Weeds present Pass Subsidence Pass

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Contouring in project area is continuous with surrounding Landscape. Vegetation appears vigorous & well established. Location meets Final Reclamation requirements. Vegetation cover and composition on location is sufficient and was assessed to be 80% of the surrounding area. No visible disturbance or debris remains.

Corrective Action: _____ Date _____

Overall Final Reclamation	Pass	Well Release on Active Location	<input type="checkbox"/>	Multi-Well Location	<input type="checkbox"/>
---------------------------	------	---------------------------------	--------------------------	---------------------	--------------------------

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674104401	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4465396