




## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	May 4, 2018 5:01:23 PM MDT
Server Receive Date:	May 16, 2018 12:40:11 PM MDT
Reference Number:	20180516-1878761322
Location:	5600 E Main St, Farmington, NM 87402, USA May 4, 2018 5:00:46 PM MDT [ <a href="#">View Map</a> ]

## Information

Name	celkins@gobrainstorm.net
Date	May 1, 2018
Well Name	WEBB-REEDER GAS UNIT B 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Contaminated Soils Removed sediment from BMP's

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos

