

**Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111**



Location Photo #1,



**Location Photo #2, Storm water issue, facing
West looking up Hill**

**Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111**



**Location Photo #3, West side of location,
looking South.**



Location Photo #4, Looking uphill facing west

**Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111**



**Location Photo #5, West side of location,
looking South.**



**Location Photo #6, Storm water issue,
Looking uphill facing west**



**Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111**



Location Photo #7, Facing North

**Location Photo #8, Storm water issue
Looking uphill facing west**

**Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111**



Location Photo #9, Ditch flowing from location to a retention pond.



Location Photo #10, In retention pond looking down hill facing South.



**Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111**



Location Photo #11, storm water issue along access road

Location Photo #12, Storm water issue along access road

**Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111**



Location Photo #13, west side of access road



Location Photo #14, Storm water issue, Looking South and downhill along access road

**Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111**



05/14/18

Location Photo #15, Facing North looking uphill along access road



**Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111**



Location Photo #16, East side of location looking down at creek in retention pond



Location Photo #17, Storm water issue near east retention pond

Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111



Location Photo #18, looking west from retention pond



Location Photo #19, Erosion on down hill side of retention pond

**Inspection Photo
Federal RWF 512-9
API# 045-12810
Inspection # 689301111**



Location Photo #20, Erosion above north end of location, looking west

Location Photo #21, Erosion on north end of location, looking West