

**Inspection Photo
Circle B Land
API# 045-12383
Inspection # 689301130**



Location Photo #1,

Location Photo #2,

**Inspection Photo
Circle B Land
API# 045-12383
Inspection # 689301130**



Location Photo #3, Signs peeling of falling off

Location Photo #4, Signs peeling or falling off

**Inspection Photo
Circle B Land
API# 045-12383
Inspection # 689301130**



Location Photo #5, Faded battery sign