

Well Name : Bullseye 2

API # : 067-09286



Photo 1: Wellhead sign previous inspection.



Photo 2: Wellhead sign.

Well Name : Bullseye 2

API # : 067-09286



Photo 3: Below grade tank labels previous inspection.



Photo 4: New tank signage.

Well Name : Bullseye 2

API # : 067-09286



Photo 5: Impacted soil around wellhead previous inspection.



Photo 6: Cleaned up area around wellhead.

Well Name : Bullseye 2
API # : 067-09286



Photo 7: Impacted soil at rear of pump jack previous inspection.



Photo 8: Cleaned up area around pump jack base.

Well Name : Bullseye 2

API # : 067-09286



Photo 9: Mineral deposits on tank heater tube hatch previous inspection.



Photo 10: Tank heater tube hatch.

Well Name : Bullseye 2
API # : 067-09286



Photo 11: Location overview.



Photo 12: Location overview.