

# Final Reclamation Inspection

May 17, 2018

Operator: EXTRACTION OIL & GAS INC - #10459

API: 05-069-06215

Inspection Document #: 682403596

Larimer County, CO

NWNW Section 31 T5N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SKAER FARM #2  
API: 05-069-06215



**Photo 1.** Photo taken from the approximate well location, facing East. Desirable vegetation was observed within the well location but several annual, weedy vegetation and noxious weeds were observed. At a minimum, Operator shall control noxious weeds and may need to perform additional reclamation activities.



Inspection Photos  
Location Name: SKAER FARM #2  
API: 05-069-06215



**Photo 2.** Photo taken from the well location, illustrating Canada thistle, List B CO Noxious weed. Operator shall control noxious weeds prior to seed set.




Inspection Photos  
Location Name: SKAER FARM #2  
API: 05-069-06215



**Photo 3.** Photo taken from the western well location, facing North. Well location is not reflective of reference area vegetative conditions. At a minimum, Operator shall control noxious weeds and may need to perform additional reclamation activities.



Inspection Photos  
Location Name: SKAER FARM #2  
API: 05-069-06215



**Photo 4.** Photo taken from the northern well location, facing North. See comments under Photo 3.