



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*), intermediate wheatgrass (*Thinopyron intermedium*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 4. View of cobble run-down within the northeastern portion of the project area.



Photo 4. View of erosional channel forming within the northern portion of the project area.