

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2018

Submitted Date:

05/18/2018

Document Number:

677900341**FIELD INSPECTION FORM**
 Loc ID 337495 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 332-3585	gjones@augustusenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286312	WELL	PR	03/13/2007	GW	125-10273	RICHES 14-16	PR

**General Comment:**Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Trail through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign for associated wells mounted to fence at meter sheds		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Metal panels around VGS and meter sheds		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 3		
Comment:	Shared meter run for Richers 14-15, 14-16 and Rockwell 14-13		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Churchill unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and telemetry equipment at meter sheds		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Vertical Separator	# 3		
Comment:	3-Vertical gas separators 50% buried by meter sheds		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	286312	Type:	WELL	API Number:	125-10273	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Richers 14-15, 14-16 and Rockwell 14-13) 570' E of wellhead								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT