

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2018

Submitted Date:

05/18/2018

Document Number:

677900352**FIELD INSPECTION FORM**

Loc ID 337523 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|----------------|---------------------------|---------|
| Jones, Greg | (970) 332-3585 | gjones@augustusenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 286587 | WELL | PR | 03/13/2007 | GW | 125-10304 | RICHES 14-15 | PR |

General Comment:Routine Inspection

Location

| | | | |
|--------------------|-------------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access wellhead through farm ground | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|--------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by unit | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------|--|--|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | |
| | Date: | | |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---------------------------------------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit and wellhead | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electric panel | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | Churchill unit | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------|--|--|--|
| Flaring: | | | |
| Type | | | |

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 286587 | Type: | WELL | API Number: | 125-10304 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Central meter run for (Richers 14-15, 14-16 and Rockwell 14-13) 2235' ESE of wellhead | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | Pass | Other | Pass | | | |

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT