

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2018

Submitted Date:

05/21/2018

Document Number:

688301814**FIELD INSPECTION FORM**

Loc ID 454833 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10660Name of Operator: K3 OIL & GAS OPERATING COMPANYAddress: 24900 PITKIN RD STE 305City: THE WOODLANDS State: TX Zip: 77386**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Rigas, John	(832) 813-8496	john.rigas@k3oil.com	President
Seligman, Eva	(832) 813-8558	eva.seligman@k3oil.com	Designated Agent
Warmath, Alex	(832) 813-5985	alex.warmath@k3oil.com	CEO

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454832	WELL	DG	05/06/2018		073-06739	James 6-3	DG

General Comment:

BOP

Inspected FacilitiesFacility ID: 454832 Type: WELL API Number: 073-06739 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: WW Rig 20 Pusher/Rig Manager: Paco
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: NO Blind Ram: NO Hydril Type: YES
Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: YES Unlined Pit: YES Closed Loop: NO Semi-Closed Loop: NO
Multi-Well: NO Disposal Location: on location

Comment: High 900 psi
Low 250 psi

Corrective Action: _____ Date: _____