

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2018

Submitted Date:

05/21/2018

Document Number:

688301837

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
451166 _____ Sherman, Susan _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 26580
Name of Operator: BURLINGTON RESOURCES OIL & GAS LP
Address: 600 N DAIRY ASHFORD RD
City: HOUSTON State: TX Zip: 77079

Findings:

- 7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
ConocoPhillips		COPColoradoReg@conocophillips.com	
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	Regulatory Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453492	WELL	DG	02/27/2018		001-10100	Big Sandy 3-65 36-31 2BH	DG
453494	WELL	DG	02/24/2018		001-10102	Big Sandy 3-65 36-31 1DH	DG

General Comment:[Frac Inspection](#)

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	location sign at gate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 453492 Type: WELL API Number: 001-10100 Status: DG Insp. Status: DG

Facility ID: 453494 Type: WELL API Number: 001-10102 Status: DG Insp. Status: DG

Well Stimulation

Stimulation Company: Halliburton Stimulation Type: OTHER
Other: XLink

Observation:

Maximum Casing Recorded: 8949 PSI Tubing: _____
Surface: _____ Intermediate: _____
Production: _____ Instantaneous Shut-In Pressure (ISIP) 3704
Bradenhead Psi: 2 Frac Flow Back: Fluid: _____ Gas: _____

Comment: Stage 4
BH well zipper fracked with DH well.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds	Pass					
Gravel	Pass	Gravel	Pass	Spill Response	Pass	
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: [Tornado shelter on location](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688301838	Conoco Phillips Big Sandy 3-65 36-31 1DH/BH Frac	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4470092
688301839	Conoco Phillips Big Sandy 3-65 36-31 Torndado Shelter	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4470093