

Well Name : Gosney 1

API # : 067-06570



Photo 1: Wellhead sign previous inspection.




Photo 2: Wellhead sign.

Well Name : Gosney 1

API # : 067-06570



Photo 3: Unused 1" gas line at separator previous inspection.



Photo 4: Locked out 1" gas line at separator.

Well Name : Gosney 1

API # : 067-06570



Photo 5: Open ended bent over 1" steel line S of wellhead previous inspection.



Photo 6: Steel 1" line cut below grade with plugged valve.

Well Name : Gosney 1

API # : 067-06570



Photo 7: Unused open ended 1" steel riser E side of domestic tap equipment previous inspection.



Photo 8: Abandoned/removed 1" steel riser on E side of domestic tap equipment.

Well Name : Gosney 1

API # : 067-06570



Photo 9: Section of abandoned flow line on E perimeter previous inspection.



Photo 10: Flow line section removed from E perimeter.

Well Name : Gosney 1  
API # : 067-06570



Photo 11: Location overview.



Photo 12: Location overview.

Well Name : Gosney 1  
API # : 067-06570



Photo 13: Location overview.



Photo 14: Location overview.