

Inspection Photos
Location Name: Dwinell 1
API: 05-057-05129



Photo 1. Casing gauge at beginning of test.



Photo 2. Casing gauge at end of test.

Inspection Photos
Location Name: Dwinell 1
API: 05-057-05129

State of Colorado
Oil and Gas Conservation Commission

MECHANICAL INTEGRITY TEST

Well Name: **DAK/LAK** API Number: **4554-5651**

Test Type: ☒ **SMALL-OR PRODUCTION WELL** ☐ **INJECTION WELL**

Test Results:

Test Type	Test Results	Test Date
Pressure Test	Pass	08/14/2018
Leak Test	Pass	08/14/2018
Flow Test	Pass	08/14/2018

Inspector: **[Signature]** Date: **08/14/2018**

Witness: **[Signature]** Date: **08/14/2018**

08/14/2018 10:47

Photo 3. Photo of test form as filled out in the field, witnessed but not passed.