

Inspection Photos  
Location Name: Duncan "B" 6  
API: 05-081-05550



**Photo 1. Overview of location taken at entrance facing northeast.**



**Photo 2. No capacity on tank.**