

Interim Reclamation Inspection

May 21, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

API: 05-123-25854

Inspection Document #: 682403608

Weld County, CO

SENW Section 34 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: TURNER #21-34
API: 05-123-25854



Photo 1. Photo taken from the northwestern interim area, facing North. Photo illustrates a cereal rye (*Secale cereale*) grass species that has established throughout the interim areas. Smooth brome is the desired grass species but little establishment was observed.

Inspection Photos
Location Name: TURNER #21-34
API: 05-123-25854



Photo 2. Photo taken from the northwestern interim area, facing East. See comments under Photo 1.

Inspection Photos
Location Name: TURNER #21-34
API: 05-123-25854



Photo 3. Photo taken from the northwestern interim area, facing South. See comments under Photo 1.

Inspection Photos
Location Name: TURNER #21-34
API: 05-123-25854



Photo 4. Photo taken west of the wells, facing East. Photo illustrates smooth brome establishment which is the desired vegetation. This is a portion of the land that was excavated from a release and topsoil was later brought in.

Inspection Photos
Location Name: TURNER #21-34
API: 05-123-25854




Photo 5. Photo taken west of the wells, facing South. Photo illustrates smooth brome establishment within the areas of excavation which is the desired vegetation with cereal rye in the background.

Inspection Photos
Location Name: TURNER #21-34
API: 05-123-25854




Photo 6. Photo taken west of the wells, facing West. See comments under Photo 5.

Inspection Photos
Location Name: TURNER #21-34
API: 05-123-25854



Photo 7. Photo taken north of the wells, facing North. In the foreground of the photo, it illustrates a patch of smooth brome establishment within the cereal rye.