

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2018

Submitted Date:

05/21/2018

Document Number:

691300205**FIELD INSPECTION FORM**Loc ID 319094 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone        | Email                                 | Comment                     |
|--------------|--------------|---------------------------------------|-----------------------------|
| Kraich, Adam | 970-420-0536 | Adam.Kraich@state.co.us               | (Area 117) Field Operations |
| ,            |              | COGCCInspections@extracti<br>onog.com | All Inspections             |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name            | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 453223      | WELL | DG     | 02/05/2018  |            | 123-45983 | Coyote Trails 34S-20-12N | DG          |
| 453231      | WELL | DG     | 02/05/2018  |            | 123-45991 | Coyote Trails 34S-20-11C | DG          |
| 453234      | WELL | DG     | 02/06/2018  |            | 123-45994 | Coyote Trails 34S-20-10N | DG          |

**General Comment:**

**Inspected Facilities**

Facility ID: 453223 Type: WELL API Number: 123-45983 Status: DG Insp. Status: DG

**Complaint**

Comment: Inspection in response to complaint.

Field Inspector Assigned: Adam Kraich

Complaint Received:

Date: 5/17/2018

Complaint Contacted:

Date: 5/17/2018 Time 14:58 AM

Location #: 319094

Inspection Document #: 691300205

Nature of complaint: Noise,

Field Inspector Actions:

On 5/11/2018, I received a complaint in regard to noise, suspected to be originating from the Coyote Trails pad, owned and operated by Extraction Oil & Gas.

On 5/17/2018, I performed an inspection of the Coyote Trails pad. During the inspections, I found the 3 wells in fracking operation; the Coyote Trails 34S-20-10N, 34S-20-11C, and the 34S-20-12N. All observed to be under pumping operations at time of inspection.

Extraction regulatory management has continuous sound auditing equipment deployed in the field around the Coyote Trails location. On 5/21/2018, the data was made available to determine compliance. No sound compliance issues were identified in the report. Please see sound audit information attached to the inspection document for details.

No violation of COGCC rules were observed at the time of the inspection.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

**Well Stimulation**

Stimulation Company: Liberty

Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI

Tubing: \_\_\_\_\_

Surface: \_\_\_\_\_

Intermediate: \_\_\_\_\_

Production: \_\_\_\_\_

Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_

Bradenhead Psi: \_\_\_\_\_

Frac Flow Back: Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 453231 Type: WELL API Number: 123-45991 Status: DG Insp. Status: DG

**Well Stimulation**Stimulation Company: LibertyStimulation Type: HYDRAULIC FRAC**Observation:**

Other: \_\_\_\_\_

Maximum Casing Recorded: \_\_\_\_\_ PSI

Tubing: \_\_\_\_\_

Surface: \_\_\_\_\_

Intermediate: \_\_\_\_\_

Production: \_\_\_\_\_

Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_

Bradenhead Psi: \_\_\_\_\_

Frac Flow Back: \_\_\_\_\_

Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 453234Type: WELLAPI Number: 123-45994Status: DGInsp. Status: DG**Well Stimulation**Stimulation Company: LibertyStimulation Type: HYDRAULIC FRAC**Observation:**

Other: \_\_\_\_\_

Maximum Casing Recorded: \_\_\_\_\_ PSI

Tubing: \_\_\_\_\_

Surface: \_\_\_\_\_

Intermediate: \_\_\_\_\_

Production: \_\_\_\_\_

Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_

Bradenhead Psi: \_\_\_\_\_

Frac Flow Back: \_\_\_\_\_

Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 691300218    | Inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4471890">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4471890</a> |
| 691300219    | Sound Audit PDF.  | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4471891">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4471891</a> |