

# Interim Reclamation Inspection

May 21, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 327882

Inspection Document #: 682403613

Weld County, CO

NESW Section 36 T4N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HSR-CONLEY #11-36A  
Location ID: 327882



Google Earth aerial imagery taken September 7, 2016 illustrating the subject well pad for this follow-up interim reclamation inspection (outlined in the green dashed line).

Inspection Photos  
Location Name: HSR-CONLEY #11-36A  
Location ID: 327882



**Photo 1.** Photo taken from the western interim area, facing North. Desirable plant species establishment is evident throughout this area and will remain in-process until it meet Rule 1003 standards. Operator mentioned weed management practices are planned and scheduled.



**Photo 2.** Photo taken from the western interim area, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: HSR-CONLEY #11-36A  
Location ID: 327882



**Photo 3.** Photo taken from the western interim area, facing South. See comments under Photo 1.