

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2018

Submitted Date:

05/17/2018

Document Number:

689701363

FIELD INSPECTION FORM

Loc ID 336005 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202

Findings:

27 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|---------------------------------------|---------------------------------|
| COGCC, Laramie | 970-248-0497 | cogccnotifications@laramie-energy.com | All inspections |
| Leonard, Mike | | mike.leonard@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 272955 | WELL | PR | 06/29/2005 | GW | 045-10201 | CASCADE CREEK 609-14 | PR |
| 297790 | WELL | PR | 11/23/2015 | GW | 045-16964 | CASCADE CREEK 697-16-09A | PR |
| 299135 | WELL | PR | 04/11/2011 | GW | 045-17571 | CASCADE CREEK 697-09-50A | PR |
| 299136 | WELL | PR | 06/10/2011 | GW | 045-17572 | CASCADE CREEK 697-16-02B | PR |
| 299137 | WELL | PR | 12/28/2010 | GW | 045-17573 | CASCADE CREEK 697-08-64B | PR |
| 299138 | WELL | PR | 04/12/2011 | GW | 045-17574 | CASCADE CREEK 697-08-56B | PR |
| 299511 | WELL | PR | 10/15/2010 | GW | 045-17693 | CASCADE CREEK 697-16-09B | PR |
| 299512 | WELL | PR | 06/10/2011 | GW | 045-17694 | CASCADE CREEK 697-09-58 | PR |
| 299513 | WELL | PR | 02/04/2011 | GW | 045-17695 | CASCADE CREEK 697-17-08A | PR |
| 299514 | WELL | PR | 10/12/2010 | GW | 045-17696 | CASCADE CREEK 697-16-01 | PR |
| 301550 | WELL | PR | 06/10/2011 | GW | 045-18175 | Cascade Creek 697-09-50B | PR |
| 301551 | WELL | PR | 04/11/2011 | GW | 045-18176 | Cascade Creek 697-17-08B | PR |
| 302106 | WELL | PR | 08/24/2015 | GW | 045-18365 | Cascade Creek 697-08-56A | PR |
| 302107 | WELL | PR | 04/11/2011 | GW | 045-18366 | Cascade Creek 697-08-64A | PR |
| 416476 | WELL | PR | 12/21/2010 | GW | 045-19277 | Cascade Creek 697-17-15 | PR |
| 416478 | WELL | PR | 04/11/2011 | GW | 045-19278 | Cascade Creek 697-09-33A | PR |
| 416480 | WELL | PR | 06/10/2011 | GW | 045-19279 | Cascade Creek 697-17-14 | PR |
| 416486 | WELL | PR | 10/10/2010 | GW | 045-19281 | Cascade Creek 697-17-06A | PR |

| | | | | | | | |
|--------|------|----|------------|----|-----------|--------------------------|----|
| 416490 | WELL | PR | 06/10/2011 | GW | 045-19282 | Cascade Creek 697-08-62B | PR |
| 416491 | WELL | PR | 04/11/2011 | GW | 045-19283 | Cascade Creek 697-09-33B | PR |
| 416493 | WELL | PR | 04/11/2011 | GW | 045-19284 | Cascade Creek 697-17-23A | PR |
| 416496 | WELL | PR | 04/11/2011 | GW | 045-19285 | Cascade Creek 697-08-54A | PR |
| 416498 | WELL | PR | 12/29/2010 | GW | 045-19286 | Cascade Creek 697-08-62A | PR |
| 416500 | WELL | PR | 12/15/2015 | GW | 045-19287 | Cascade Creek 697-08-54B | PR |

General Comment:

[Routine General Field Inspection](#)

Location

Lease Road:

| | | | |
|--------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|------------|
| Comment: | 970-248-0497. Number no longer in service message when called. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 06/20/2018 |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL | 1 | <50 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 4 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | |
| | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | |
| | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 272955 | Type: | WELL | API Number: | 045-10201 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 297790 | Type: | WELL | API Number: | 045-16964 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 299135 | Type: | WELL | API Number: | 045-17571 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 299136 | Type: | WELL | API Number: | 045-17572 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 299137 | Type: | WELL | API Number: | 045-17573 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 299138 | Type: | WELL | API Number: | 045-17574 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 299511 | Type: | WELL | API Number: | 045-17693 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 299512 | Type: | WELL | API Number: | 045-17694 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |

| | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 299513 | Type: | WELL | API Number: | 045-17695 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 299514 | Type: | WELL | API Number: | 045-17696 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 301550 | Type: | WELL | API Number: | 045-18175 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 301551 | Type: | WELL | API Number: | 045-18176 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 302106 | Type: | WELL | API Number: | 045-18365 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 302107 | Type: | WELL | API Number: | 045-18366 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 416476 | Type: | WELL | API Number: | 045-19277 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | 416478 | Type: | WELL | API Number: | 045-19278 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | Date: | |
| Corrective Action: | | | | | | | | Date: | |

| | | | | |
|-----------------------|----------------|-----------------------|------------|------------------|
| Facility ID: 416480 | Type: WELL | API Number: 045-19279 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 416486 | Type: WELL | API Number: 045-19281 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 416490 | Type: WELL | API Number: 045-19282 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 416491 | Type: WELL | API Number: 045-19283 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 416493 | Type: WELL | API Number: 045-19284 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 416496 | Type: WELL | API Number: 045-19285 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 416498 | Type: WELL | API Number: 045-19286 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 416500 | Type: WELL | API Number: 045-19287 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | | | Material Handling And Spill Prevention | Pass | |
| Berms | Pass | | | | | |
| | | Ditches | Pass | | | |
| | | Gravel | Pass | | | |
| Gravel | Pass | | | | | |
| Compaction | Pass | | | | | |
| | | Compaction | Pass | | | |
| | | Culverts | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 401643486 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4465649 |
| 689701367 | Inspection 689701363 photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4465637 |