

Inspection Photos

Location Name: Zimmerman- 65N67W / 17SWSW

Location #: 331822



Photo #1

Zimmerman #14-17 (API 05-123-21351) wellhead



Photo #2

Zimmerman 14-17 & 23-17 battery



Inspection Photos

Location Name: Zimmerman- 65N67W / 17SWSW

Location #: 331822



Photo #3

Zimmerman 14-17 & 23-17 East gas meter run

**Gas meter run is disconnected and considered
unused equipment**

