

Inspection Photos
Location Name: Dilka 21-6
API: 05-123-23785



Photo 1: Location



Photo 2: Wellhead



Inspection Photos
Location Name: Dilka 21-6
API: 05-123-23785



Photo from prior inspection for comparison



Photo 3: Stained soil in separator house

Inspection Photos
Location Name: Dilka 21-6
API: 05-123-23785



Photo 4: Stained soil at wellhead



Photo 5: Unmarked tank