

Final Reclamation and Stormwater Inspection

May 17, 2018

Operator: SUNDANCE ENERGY INC #10340

Location ID: 318136

Inspection Document #: 674902094

Weld County, CO

NENW Section 24 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sundance Energy /2N68W24
Location ID: 318136



Photo 1. Photo taken from the location entrance facing South. The reclamation operations have failed to generate perennial vegetation cover. Entire disturbance area is currently annual weeds including, field bindweed, redstem filaree, and cheatgrass.



Photo 2. Photo taken from well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Sundance Energy /2N68W24
Location ID: 318136



Photo 3. Photo taken on April 1 2002 obtained from USGS showing the disturbance area of approximately 0.1 acres.



Photo 4. Google Earth Street View imagery from September 2012 showing disturbance area.