

# Inspection Photos

05/24/2018

Operator: CM PRODUCTION LLC - 10352

Location ID: 317369

Inspection Doc. Number: 682503377

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: CM PRODUCTION LLC - 10352  
Location ID: 317369



**Photo 1:** Photo taken east end of the tank battery facility, facing southwest. Photos 1-4 show an overview of the location, facing southwest, to west, to north. Vegetation seen on location predominantly sand dropseed, native forbs and cheatgrass.



**Photo 2:**



Inspection Photos  
Operator: CM PRODUCTION LLC - 10352  
Location ID: 317369



**Photo 3:**



**Photo 4:** Photo taken from the northwest end of the well. Photo shows undesirable weedy plant establishment around areas of the well location





**Photo 5:** Photo taken from the south end of the well, facing north. Photo shows undesirable weedy plant establishment around areas of the well location



**Photo 6:** Photo taken from the northwest anchor of the location. Small patches of kochia germination and establishment can be observed at the anchors.





**Photo 7:** Photo taken from the Cannon 1-24 well, ~ ¼ mile east of the Cannon 33-24 (well in this inspection). Photo shows access road leading to the well has been plowed over.



**Photo 8:** Aerial imagery showing areas where undesirable weedy plant species, such as kochia, were observed in higher densities. Areas are 0.15 acres in size, conservatively.