

Inspection Photos

05/24/2018

Operator: CM PRODUCTION LLC - 10352

Location ID: 317255

Inspection Doc. Number: 682503381

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: CM PRODUCTION LLC - 10352
Location ID: 317255



Photo 1: Photo taken from the north end of the location, facing southeast. Photos 1-3 show an overview of the location, facing southeast, to south, to north. Vegetation seen on location predominantly sand dropseed, smooth brome native forbs and cheatgrass.



Photo 2:



Photo 3:



Photo 4: Photo taken from the north end of the location, facing north. Photo shows access road appears to be in good condition.

Inspection Photos
Operator: CM PRODUCTION LLC - 10352
Location ID: 317255



Photo 5: Photo taken from the west end of the well, facing east. Photo shows undesirable weedy plant establishment around areas of the well location



Photo 6: Photo taken from the southwest end of the well, facing east. Photo shows undesirable weedy plant establishment around areas of the well location




Photo 7: Aerial imagery showing areas where undesirable weedy plant species, such as kochia, were observed in higher densities. Areas are 0.1 acres in size, conservatively.