

Final Reclamation and Stormwater Inspection

May 17, 2018

Operator: SUNDANCE ENERGY INC #10340

Location ID: 318125

Inspection Document #: 674902103

Weld County, CO

SWNW Section 24 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sundance Energy /2N68W24
Location ID: 318125



Photo 1. Photo taken from the entrance of the location, facing Northeast. This location is not in compliance with Rule 1004. Gravel remains throughout the location and access road and Wood debris remains on site in the gravel. Weedy, annual vegetation was observed which includes but not limited to cheatgrass.



Photo 2. Photo taken from well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: Sundance Energy /2N68W24
Location ID: 318125



Photo 3. Photo taken at location. Debris needs removal. See comments under Photo 1.



Photo 4. Photo taken from location, facing West. Tank battery has not been removed. See other comments under Photo 1.