

Final Reclamation and Stormwater Inspection

May 17, 2018

Operator: PDC ENERGY INC – 69175

Location ID: 323254

Inspection Document #: 674902107

Weld County, CO

NWNE Section 24 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PDC Energy /2N68W24
Location ID: 323254



Photo 1. Photo taken from the entrance of the location, facing North. Location appears to be in process of final reclamation. A List B CO Noxious weed, Canada thistle, was observed on location.



Photo 2. Photo taken from reference location, facing North. See comments under Photo 1.