

**Inspection Photos**  
**Location Name: YF-3**  
**API: 05-083-06593**  
**REM #9859**



**YF-3 location sign.**



**Previous location of YF-3 drilling pit.**

**Inspection Photos**  
**Location Name: YF-3**  
**API: 05-083-06593**  
**REM #9859**



**Gypsum amended soil where exceedances of Table 910-1 standards were found.**



**Southern edge of YF-3 location.**